you must submit the information described in  $\S63.6(g)(2)$ .

## §63.7906 How do I demonstrate initial compliance with the emissions limitations or work practice standards for surface impoundments?

- (a) You must demonstrate initial compliance with the emissions limitations and work practice standards in §63.7905 that apply to your affected surface impoundments by meeting the requirements in paragraphs (b) and (c) of this section, as applicable to your surface impoundments.
- (b) You must demonstrate initial compliance of each surface impoundment using a floating membrane cover according to §63.7905(b)(1) if you have submitted as part of your notification of compliance status, specified in §63.7950, a signed statement that you have met the requirements in paragraphs (b)(1) through (3) of this section.
- (1) You have installed a floating membrane cover and closure devices that meet the requirements in §63.942(b), and you have records documenting the design and installation.
- (2) You will operate the cover and closure devices according to the requirements in §63.942(c).
- (3) You have performed an initial visual inspection of each surface impoundment and closure devices according to the requirements in §63.946(a), and you have records documenting the inspection results.
- (c) You must demonstrate initial compliance of each surface impoundment using a cover vented to a control device according to \$63.7905(b)(2) if you have submitted as part of your notification of compliance status, specified in \$63.7950, a signed statement that you have met the requirements in paragraphs (c)(1) through (4) of this section.
- (1) You have installed a cover and closure devices that meet the requirements in §63.943(b), and have records documenting the design and installation
- (2) You will operate the cover and closure devices according to the requirements in  $\S63.943(c)$ .
- (3) You have performed an initial visual inspection of each cover and closure devices according to the require-

ments in §63.946(b), and have records documenting the inspection results.

(4) You have met each applicable requirement for demonstrating initial compliance with the emission limitations and work practice standards for a closed vent system and control device in §63.7926.

## § 63.7907 What are my inspection and monitoring requirements for surface impoundments?

- (a) If you use a floating membrane cover according to \$63.7905(b)(1), you must visually inspect the floating membrane cover and its closure devices at least annually according to the requirements in \$63.946(a).
- (b) If you use a cover vented to a control device according to \$63.7905(b)(2), you must meet requirements in paragraphs (b)(1) and (2) of this section.
- (1) You must visually inspect the cover and its closure devices for defects according to the requirements in §63.946(b).
- (2) You must monitor and inspect the closed vent system and control device according to the requirements in §63.7927 that apply to you.

## §63.7908 How do I demonstrate continuous compliance with the emissions limitations and work practice standards for surface impoundments?

- (a) You must demonstrate continuous compliance with the emissions limitations and work practice standards in §63.7905 applicable to your affected surface impoundments by meeting the requirements in paragraphs (b) and (c) of this section as applicable to your surface impoundments.
- (b) You must demonstrate continuous compliance for each surface impoundment using a floating membrane cover according to \$63.7905(b)(1) by meeting the requirements in paragraphs (b)(1) through (5) of this section.
- (1) Operating and maintaining the floating membrane cover and closure devices according to the requirements in §63.942(c).
- (2) Visually inspecting the floating membrane cover and closure devices for defects at least annually according to the requirements in §63.946(a).
- (3) Repairing defects according to the requirements in §63.946(c).